

TRI-PARTY AGREEMENT

Change Notice Number TPA-CN- 661	TPA CHANGE NOTICE FORM	Date: July 27, 2015
Document Number, Title, and Revision: Removal Action Work Plan for the Deactivation, Decontamination, Decommissioning, and Demolition of the Plutonium Finishing Plant Complex, Revision 0		Date Document Last Issued: July 2014
Originator: W.G. Cox		Phone: 372-9345

Description of Change:

Modification of Figure 5-1 to update TPA Interim Milestone Wording Change per TPA Change Form M-83-15-01.

T.K. Teynor and S. Schleif agree that the proposed change
DOE Lead Regulatory Agency
 modifies an approved workplan/document and will be processed in accordance with the Tri-Party Agreement Action Plan, Section 9.0, *Documentation and Records*, and not Chapter 12.0, *Changes to the Agreement*.

Figure 5-1 on page 5-1 text is modified to match Milestone M-083-44 language per TPA Change Form M-83-15-01 'Modify facility disposition activities of milestone M-083-44 to reflect a safer, more efficient sequence of transitioning the above-grade portions of the PFP facilities to deactivation and demolition'.

Figure 5-1 is attached.

Modifications are denoted by using ~~strikeout~~ to indicate text deletions and double underline to indicate text additions.

Justification and Impacts of Change:

This change modifies the work plan to align with the milestone description per TPA Change Form M-83-15-01.

Approvals:

T.K. Teynor

DOE Project Manager
NA

Date

July 30, 2015 ☒ Approved ☐ Disapproved

☐ Approved ☐ Disapproved

EPA Project Manager

S. Schleif

Ecology Project Manager

Date

8/18/15

Date

☒ Approved ☐ Disapproved

5 Project Management

This chapter describes overall project management elements for the PFP removal action.

5.1 Project Team

The project team includes the individuals working to accomplish the removal action. Accordingly, the project team includes a DOE Project Manager representing the Lead Agency, an Ecology Project Manager representing the Lead Regulatory Agency and a Contractor Project Manager.

The DOE Project Manager is responsible for monitoring the technical/scope, cost, and schedule baselines through all phases of this removal action.

The Ecology Project Manager is responsible for regulatory oversight.

The Contractor Project Manager has overall responsibility and accountability for the performance of all activities associated with this removal action.

5.2 Project Cost and Schedule Tracking

The demolition of structures is part of the overall TPA (Ecology et al., 1989a) milestone M-083-00A completion schedule. This overall schedule is provided as Figure 5-1. This schedule is subject to acceleration or delay due to changes in priority as determined by the TPA (Ecology et al., 1989a) signatories and consistent with the TPA change processes.




Figure 5-1. Project Schedule

Cost and schedule tracking is managed in accordance with Section 4 of the TPA (Ecology et al., 1989a).

5.3 Security Requirements

Access to the Hanford Site is controlled by fences and around the clock checkpoints on vehicle access roads. All personnel entering the Hanford Site must display a DOE issued identification badge. Personnel on the Hanford Site are also subject to random searches. Signs at the 200 West Area boundaries indicate access by authorized personnel only or similar legends.